




MOBILI DI SERVIZIO BRIDGET




B1
L.25/35/50 P.55




B2
L.35/50 P.55




B2B
L.35/50 P.55



B2C
L.35/50 P.55




B3
L.35/50 P.55




B3B
L.35/50 P.55


MOBILI DI SERVIZIO BRIDGET




B3C
L.35/50 P.55




B3D
L.35/50 P.55




B3E
L.35/50 P.55



B4
L.35/50 P.55




B4B
L.35/50 P.55




B4C
L.35/50 P.55


MOBILI DI SERVIZIO BRIDGET




B4D
L.35/50 P.55




B4E
L.35/50 P.55




B4F
L.35/50 P.55



B5
L.35/50 P.55




B5B
L.35/50 P.55




B5C
L.35/50 P.55


MOBILI DI SERVIZIO BRIDGET




B5D
L.35/50 P.55




B5E
L.35/50 P.55




B6
L.35/50 P.55



B6B
L.35/50 P.55




B6C
L.35/50 P.55




B7
L.35/50 P.55


MOBILI DI SERVIZIO BRIDGET




B7B
L.35/50 P.55



B8
L.35/50 P.55



B9
L.35/50 P.55



BAR
L.35/50 P.55